

MARTEAU & CO

CONDITION REPORT

The following describes the condition of the watch below, as it was when the watch was included in the catalogue: The Heat Wave

Lot 31

Daniel Roth - Chronograph Ref. S247

Condition : A charming chronograph, this S247 is offered in very good overall condition. Its case and lugs retain sharp definition and attractive surfaces, showing only a minimal, superficial marks on the bezel that are consistent with the age of the watch. The crown and pushers are original and very well preserved, while the chronograph function is performing well at the time of cataloging. The hallmarks are deep and visible on the underside of the lugs, while the case still retains its original shape and proportions.

The condition and relative wear of the watch are faithfully represented in the photographs provided. We invite interested collectors to reach out to info@marteauandco.com with any questions or to request further images.