MARTEAU & CO

CONDITION REPORT

The following describes the condition of the watch below, as it was when the watch was included in the catalogue: The Blueprint

Lot 7

Massena Lab x Raul Pagès - Magraph

Condition : Offered in excellent overall condition, the present Magraph shows no discernible signs of wear. The dial is in perfect condition, and shows no signs of tarnishing. The hands are also free from any signs of imperfections and have been well preserved. The movement, including the small seconds function, is in excellent condition and running at time of cataloging.

The condition and relative wear of the watch are faithfully represented in the photographs provided. We invite interested collectors to reach out to info@marteauandco.com with any questions or to request further images.

M&CO